

Under Review Notification

Raised By: Ketan Tailor

Product #: C10-23K

Date: 20.06.03

Product Name: Stationary Keeper

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank								Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
C10-23K	C10-23K REV. 1	N	Y	N	Y	Y	Y	N	N	2020-568	Drawing Update

Description of Issue:

Add chamfers on certain edges
 Redimension position of 0.380 DIA hole
 Modify 0.878 DIA boss in order to avoid interference with Side Plates

Sales may quote and sell this product
 Planning may create work orders with Engineering sign off

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Purchasing Manager

Technical Support

Product Manager - Solutions Provider

Supply Chain Director / Senior Buyer

Marketing Eugene